

PAT TEST REPORT



Test Status: All, Test Type: All
Person: All, Instrument: All
From: 13/10/2009 To: 13/10/2009

Client: LETTINGS	Site: 56 DENBIGH STR	Location: FLAT 6	
Asset ID: 01	Description: TOASTER	User: JACQUES	Test Instrument: Y30-0783
Comments: BELLINI 13AMP			

Test Type	Date	Result	Unit	Status
Visual	13/10/2009			Pass
Earth Current	13/10/2009	25	A	Information
Earth	13/10/2009	0.04	Ohm	Pass
Insulation	13/10/2009	>99.99	MOhm	Pass
Leakage	13/10/2009	<0.1	mA	Pass
Load	13/10/2009	0.81	kVA	Information
				Overall: Pass

Asset ID: 02	Description: KETTLE	User: JACQUES	Test Instrument: Y30-0783
Comments: BELLINI 13AMP			

Test Type	Date	Result	Unit	Status
Visual	13/10/2009			Pass
Earth Current	13/10/2009	25	A	Information
Earth	13/10/2009	0.04	Ohm	Pass
Insulation	13/10/2009	>99.99	MOhm	Pass
Leakage	13/10/2009	<0.1	mA	Pass
Load	13/10/2009	2.43	kVA	Information
				Overall: Pass

Asset ID: 03	Description: WASHING MACHINE	User: JACQUES	Test Instrument: Y30-0783
Comments: ZANUSSI 13AMP			

Test Type	Date	Result	Unit	Status
Visual	13/10/2009			Pass
				Overall: Pass

Asset ID: 04	Description: OVEN	User: JACQUES	Test Instrument: Y30-0783
Comments: FAGOR 13AMP			

Test Type	Date	Result	Unit	Status
Visual	13/10/2009			Pass
				Overall: Pass

Asset ID: 05	Description: COOKER HOOD	User: JACQUES	Test Instrument: Y30-0783
Comments: BUDERUS 13AMP 3AMP N/F			

Test Type	Date	Result	Unit	Status
Visual	13/10/2009			Pass
				Overall: Pass

Asset ID: 06	Description: FRIDGE/FREEZER	User: JACQUES	Test Instrument: Y30-0783
Comments: BOSCH 13AMP			

Test Type	Date	Result	Unit	Status
Visual	13/10/2009			Pass
				Overall: Pass

Asset ID: 07	Description: HOB IGNITION	User: JACQUES	Test Instrument: Y30-0783
Comments: BUDERUS N/A AMP			

Test Type	Date	Result	Unit	Status
Visual	13/10/2009			Pass
				Overall: Pass

Total Tests: 7